

US EPA ARCHIVE DOCUMENT

LANDFILL SITE ASSESSMENT

Facility Name :	Chastang Landfill	Facility Location ID :	110034132686
Assessment Date :	9/18/2010	Incident Name :	BP Spill
Physical Location :	17045 Highway 43		
City, State :	Mount Vernon , AL	County :	Mobile

ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Additional Comments : During this operational period Parvez Mallick (EPA) conducted a telephone site assessment with Matt East, Operations Manager of the Chastang Landfill, Mt. Vernon, Mobile County, Alabama. Two oily contaminated loads arrived today.	